



Designers, Manufacturers & Suppliers of Quality Height Safety & Rescue Equipment, Training & Consultancy

TRIPOD USER INSTRUCTIONS – T03

The tripod is designed to give a strong, stable and portable anchorage point for fall arrest and recovery systems. Used with a fall arrest device and or a winch, the tripod is the basis of a confined space entry and rescue system. One worker can set up the sturdy, but lightweight aluminium tripod. Leg clamps can be supplied to fit any configuration of equipment.

The tripod can have up to 6 anchor points all tested to EN795:1997. The 3 overhead pulleys can all accommodate rope up to 11mm diameter. This allows one pulley for the user and two pulleys for the rescuer allowing the rescuer to be double roped whilst recovering the user.

Optional: Three eyebolts can attach below the head and used for fall arrest and or recovery. These extra anchor points may be used with pulleys for airlines, communication lines, medical kits, tool kits, etc.

Mechanical prusik and automatic belay devices may be attached to the eyebolts. The eyebolts may also be used to anchor the tripod with anchor ropes.

Maximum Height:	2.4 Metres
Height Closed:	1.4 Metres
Maximum Base:	1.7 Metres
Minimum Base:	1.1 Metres
Weight:	19.4kg
Safe Working Load:	250kg
Safety Ratio:	6:1
Conformance:	BSEN 795 TYPE B

A competent and trained person should examine the Tripod on a regular basis. An emergency plan should be in place to deal with any emergencies that could arise during the work being carried out.

Ensure the tripod is in a serviceable condition and operates correctly before it is used.

Open the legs ensuring that the leg pins lock into position.

To raise the height of the Tripod remove a leg clip, pull out the lower leg and push the leg clip through the leg location hole in both the upper and lower leg. Repeat on the remaining legs. If being used on an uneven surface the height of each leg may be adjusted to compensate.

No other alterations should be made or additions without manufacturers prior written consent. The tripod should not be used outside its limitations, or for any purpose other than for which it is intended.

A padded tripod bag is also available to stop the unit being scratched and damaged.

Tripod should be returned to the manufacturer annually for service and recertification.

If in any doubt as to the serviceability of this equipment remove from service and contact P&P.